

was being used to pull a barge along the dock, the cable snapped and the employee was struck on the head. The wire line cable used on the winch was 3/4-inch diameter. The manufacture required a 7/8-inch diameter for the winch. The employee later died from head trauma after being transported to the hospital.

Keywords: struck by, head, grain elevator, broken cable

| | Inspection | | | Degree | Nature | Occupation |
|---|-------------|--|--|----------|--------|-------------------------------|
| 1 | 1252112.015 | | | Fatality | Other | Laborers, except construction |

UNITED STATES
DEPARTMENT OF LABOR

Occupational Safety and Health Administration
200 Constitution Ave NW
Washington, DC 20210
📞 800-321-6742 (OSHA)
TTY
www.OSHA.gov

FEDERAL GOVERNMENT

White House
Severe Storm and Flood Recovery Assistance
Disaster Recovery Assistance
DisasterAssistance.gov
USA.gov
No Fear Act Data
U.S. Office of Special Counsel

OCCUPATIONAL SAFETY AND HEALTH

Frequently Asked Questions
A - Z Index
Freedom of Information Act
Read the OSHA Newsletter
Subscribe to the OSHA Newsletter
OSHA Publications
Office of Inspector General

ABOUT THE SITE

Freedom of Information Act
Privacy & Security Statement
Disclaimers
Important Website Notices
Plug-Ins Used by DOL
Accessibility Statement